

### Late of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA
Division Director

### Inspection Report Minerals Regulatory Program

August 18, 2005

Supervisor Dort

Mine Name: ML 27618 Operator Name: The Bug House/ Loy Crapo	Permit number: S/025/025 Inspection Date: August 2, 2005 Time: 3:30 PM- 4:00 PM Weather: Warm, Cloudy		
Inspector(s): Doug Jensen, Tom Munson, Dan Smith Other Participants: None Mine Status: Active			
Elements of Inspection	Evaluated	Comment	Enforcement
<ol> <li>Permits, Revisions, Transfer, Bonds</li> <li>Public Safety (shafts, adits, trash, signs, highwalls)</li> <li>Protection of Drainages / Erosion Control</li> <li>Deleterious Material</li> <li>Roads (maintenance, surfacing, dust control, safety)</li> <li>Concurrent Reclamation</li> <li>Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)</li> </ol>			
<ul><li>8. Water Impoundments</li><li>9. Soils</li></ul>			

#### **Purpose of Inspection:**

10. Revegetation11. Air Quality12. Other

Site familiarization

#### **Inspection Summary:**

Recontouring and seeding (according to Tom) of some parts of the western portion of the mining site have been completed. There are still some areas in this section that were recently disturbed and still require reclamation.

Recent mining has also taken place on the eastern border of this permit area. The mining in this area also enters into a mineral lease belonging to Robert Harris (S/025/006). In the field it is impossible to tell where one lease ends and the other begins. A GPS map, produced by Dan, makes separation of these two leases much easier. A GPS map of this overlapping disturbance was made in order to assign the disturbed acreage to these two permits.

#### 1. Permits, Revisions, Transfer, Bonds

The total disturbed acreage in this permit area totals 6.82 acres. None of the recontoured/reseeded areas have been released as far as our records show. Because the total disturbance at the site is greater that than the 5 acre limits dictated by the approved small mine permit, the operator should complete and submit a NOI-LMO as soon as possible. A cessation order has been issued to the operator because the site has exceeded the five acre limit.



Inspection Date: August 2, 2005; Report Date: August 18, 2005

Page 2 of 2 S/025/025

As we were leaving the area, we met Mr. Crapo, who was unloading a track-hoe. He indicated that he was planning to resume mining on the eastern portion of his permit. He also indicated that a second trackhoe would be arriving on-site and work in conjunction with the trackhoe he was unloading.

#### **Conclusions and Recommendations:**

Because this site has disturbances greater than the five acres allowed by his permit, I think that the on-site meeting with all concerned parties should take place as soon as possible.


Inspector's Signature Date: 8/24/05


dj:jb

cc: Loy Crapo, Operator

Will Stokes, SITLA (ML 27618

Attachment: GPS & Photos





## Mine Number: S250025 Mine Name: ML 27618

Township 40 S Range 08 W Section 36 SLBM

Inspection Date Aug 2, 2005 Map Produced by DKS


2.16 3.06 5.22 000 Total Acres Distrubed Acres Reclaimed Acres Excluded Acres Disturbed Acres Regraded Acres Seeded



Acres Prelaw

Legend All items symbolized in legend may not be appear on map --- Township or range line: location doubtful Section line: location doubtful --- County Boundary --- Township or range Line Section line Reclaimed Disturbed Regraded Excluded Seeded Unimproved Road Secondary Route =: Main Dirt Road Primary Route State Route - US Route Other Mine

# DOQ imagery date 1998





625

Dept. of Natural Resources Division of Oil, Gas, and Mining Mineral Mines Program

Scale 1:7,500 (verify scale) 1 inch = 625 feet Different data sources and input scales may cause misalignment of data layers. This product may not meet DOGM standards for accuracy and content.